1. Ensure that surface where part is to be installed is dry and free of any wax or oil by cleaning surface thoroughly with supplied alcohol pad.
2. Remove protective liner from each piece of tape.
3. Install part in desired location and apply firm pressure to develop better adhesive contact.
4. Ideal tape application temperature range is 70°F to 100°F (21°C to 38°C). Initial tape application to surfaces below 50°F (10°C) is **not** recommended because the adhesive becomes too firm.